


Square lead screw nuts



DST-SHT-1210

SHT-1210-TR



Order key

Order example

DST-SHT-1210-DS10x12- J - □

High helix thread	SHT linear module	Installation size	Thread	iglidur® material	Hand of rotation
-------------------	-------------------	-------------------	--------	-------------------	------------------

Options:

Hand of rotation

RH: Right-Hand

LH: Left-hand

Dimensions

Part No.	Hand of rotation		Thread d1xP	From SHT linear module	
	right	left			
DST-SHT-1210-DS10x12-J-□	●	●	Ds10x12	SHT-12	► Page 1372
DST-SHT-1210-DS10x25-J-□	●	●	Ds10x25	SHT-12	► Page 1372
DST-SHT-1210-DS10x50-J-□	●	●	Ds10x50	SHT-12	► Page 1372
SHT-1210-TR10X2-J-□	●	●	Tr10x2	SHT-12	► Page 1372
SHT-1210-TR10X3-J-□	●	●	Tr10x3	SHT-12	► Page 1372


Part number suffix LH for left-hand thread, RH for right-hand thread

Lead screw nuts with flange



DST-SHT-2018

SHT-2018-TR



Please note: not symmetrical



Order key

Order example

DST-SHT-2018-DS18x24- J - □

High helix thread	SHT linear module	Installation size	Thread	iglidur® material	Hand of rotation
-------------------	-------------------	-------------------	--------	-------------------	------------------

Options:

Hand of rotation

RH: Right-Hand

LH: Left-hand

Dimensions

Part No.	Hand of rotation		Thread d1xP	From SHT linear module	
	right	left			
DST-SHT-2018-DS18x24-J-□	●	●	Ds18x24	SHT-20	► Page 1372
DST-SHT-2018-DS18x40-J-□	●	●	Ds18x40	SHT-20	► Page 1372
DST-SHT-2018-DS18x80-J-□	●	●	Ds18x80	SHT-20	► Page 1372
DST-SHT-2018-DS18x100-J-□	●	●	Ds18x100	SHT-20	► Page 1372
SHT-2018-TRM-18X4-□	●	●	Tr18x4	SHT-20	► Page 1372
SHT-2018-TRM-18X8-□	●	●	Tr18x8p4	SHT-20	► Page 1372

Part number suffix LH for left-hand thread, RH for right-hand thread